



**Provincia
di Pesaro e Urbino**

I - 61121 Pesaro, viale Gramsci 4
tel.: 0721.359.1 - fax: 0721.359.441
www.provincia.pu.it

Class. 004-6
Fasc. 12/2022

Prot. n. 11932/2023

SELEZIONE PUBBLICA, PER ESAMI, PER LA FORMAZIONE DI UNA GRADUATORIA DI IDONEI ALL'ASSUNZIONE, A TEMPO DETERMINATO, DI PERSONALE DOTATO DI SPECIFICA PROFESSIONALITA', CON PROFILO DI "FUNZIONARIO TECNICO (ingegnere o architetto)", DI CAT. D, A VALERE SUI FONDI DEL PIANO NAZIONALE DI RIPRESA E RESILIENZA (PNRR)

PUBBLICAZIONE TRACCE PROVA ORALE.

GRUPPO A –

- 1) Ai sensi dell'art. 30 del D. Lgs. 50/2016, quali sono i principi per l'aggiudicazione e l'esecuzione di appalti e concessioni?
- 2) Definizione di Progetto definitivo ai sensi dell'art. 23 del D. Lgs. 50/2016.
- 3) Ai sensi dell'art. 92 del D. Lgs. 81/2008, chi è il soggetto che ha l'obbligo di sospendere, in caso di pericolo eminente, direttamente riscontrato, le singole lavorazioni fino alla verifica degli avvenuti adeguamenti effettuati dalle imprese interessate?
- 4) Cosa accerta la verifica del progetto?
- 5) Ai sensi del DM 23/06/2022, quali sono gli ambiti di applicazione dei CAM per i servizi di progettazione ed esecuzione lavori?
- 6) Ai sensi del DM 23/06/2022, cos'è la relazione CAM?

GRUPPO B –

- 1) Ai sensi del D.M. 18 dicembre 1975, quali caratteristiche devono avere gli spazi per i servizi igienico-sanitari destinati a scuole secondari di secondo grado?
- 2) Ai sensi del D.M. 18 dicembre 1975, quali caratteristiche generali e di ampiezza devono avere le aree destinate alla costruzione di scuole secondarie di secondo grado?
- 3) Ai sensi del D.M. 18 dicembre 1975, quali caratteristiche devono avere gli spazi per le mense?
- 4) Come si realizza la programmazione dell'edilizia scolastica?
- 5) Competenze delle Province in materia di edilizia scolastica.
- 6) Ai sensi del DM 26/08/1992, quando una scuola si definisce di tipo 0 e quali norme di sicurezza vanno seguite?

GRUPPO C –

- 1) Quali sono i criteri del DNSH?
- 2) Quali sono i regimi previsti dal DNSH?
- 3) Quali sono le funzioni spettanti alle Province?
- 4) Definizione di accertamento in entrata.
- 5) Definizione di impegno di spesa.
- 6) A quale scopo le amministrazioni adottano il piano triennale delle opere pubbliche?

Traduzione dalla lingua inglese a quella italiana di articoli su materie edilizie:

1) Adjacent to the south of the renovated ice rink from the early 1980s, there is now a new two-storey functional building as well as areas for the new energy-efficient ice technology. On the ground floor, the functional building contains a strap-on room for public skating in the ice rink, the entrance area as well as skate rental and WC facilities. The upper floor houses changing rooms and sanitary facilities, a snack area and modern street.

2) In the newly constructed connecting wing was built to the highest standards of energy efficiency. The outer shells of the new buildings are constructed in a reinforced concrete-wood mix, which combines the advantages of solid constructions in terms of storage masses with the advantages of wood as a sustainable raw material. The roof was designed to be green in order to prevent urban heat build-up.

3) The ice recovery system was also brought up to date. Previously, the waste heat released by the ice production process was discharged unused. With the new energy concept, the sports and fun hall and the connecting wing will be heated and supplied with hot water from autumn to spring by means of component activation. In the future, the energy quantities will be sufficient to also feed the supermarket that is in the planning stage and other new buildings.

4) The Recovery and Resilience Facility will support the recovery plan for Europe through post-pandemic reform and investments across the EU while enabling a digital and environmental transition in a cohesive society throughout Europe. To access the RRF funds, Member States must submit their Recovery and Resilience Plan to the European Commission, which will check the alignment must allocate a minimum of 37% to climate investment and reforms and minimum of 20% to digital transition.

5) The athletics track located inside the "Facone e Borsellino" multipurpose facility underwent a necessary redevelopment. The facility, which was built in the second half of the 1980s, is equipped with an eight-lane track with stands for approximately 1,000 people, large changing room and service areas for warming up athletes. Until last year, however, the facility could not be used to its full potential: the deterioration of the synthetic surface of the track and platforms, combined with the lack of much of the fixed and mobile equipment that was worn out or missing made it difficult to use even for training.

6) In order to make a facility functional again, before it was completely deteriorated and completely unusable, it was necessary to proceed with an intervention to resurface the synthetic floor of the track. In the intervention involved the complete removal of the existing surface and the construction of a new sub-base which was completed by laying the new surface. The same considerations apply to the long and triple jump platform, the high jump platform and the javelin platform, for which, in order to bring their performance characteristics into compliance with the prescription of the FIDAL technical circular letter, it was necessary to substantially resurface the existing ground.

Il Segretario generale
(Dott. Michele Cancellieri)

(Sottoscritto digitalmente ai sensi dell'art. 21 D.Lgs. n. 82/2005 e s.m.i.)